






Aeroflex (MACOM Technology Solutions)

MABA-009852-CF1A40

| | |
|-----------------------|--|
| Part Number: | MABA-009852-CF1A40 |
| Manufacturer / Brand: | Aeroflex (MACOM Technology Solutions) |
| Mombamomba ny vokatra | BALUN 5MHZ-120MHZ 75/75 5SMD |
| Datasheets: |  MABA-009852-CF1A40.pdf |
| RoHS Status: |  Lead free / RoHS compliant |
| Ship From: | Hong Kong |
| Shipment Way: | DHL/Fedex/TNT/UPS/EMS |


MANGATAHA FAMPISEHOANA

Solutions



Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.













Specifications of MABA-009852-CF1A40

| | |
|--|--|
| PART NUMBER | MABA-009852-CF1A40 |
| MANUFACTURER | Aeroflex (MACOM Technology Solutions) |
| DESCRIPTION | BALUN 5MHZ-120MHZ 75/75 5SMD |
| LEAD FREE STATUS / ROHS STATUS | Lead free / RoHS compliant |
| TAKELA-DAZA |  MABA-009852-CF1A40.pdf |
| SERIES | - |
| MIVERINA MITSOAKA (MIN) | 19dB |
| DINGANA FIVOAHANA | - |
| FONOSANA | Cut Tape (CT) |
| PACKAGE / CASE | 5-SMD, No Lead |
| ANARANA HAFA | 1465-1696-1 |
| TENDROMBOHITRA | Surface Mount |
| NY HAAVON'NY FAHITAN-TORY (MSL) | 1 (Unlimited) |
| LEAD FREE STATUS / ROHS STATUS | Lead free / RoHS Compliant |
| ADI-HEVITRA MITOKA-MONINA (MAX) | 0.4dB |
| IMPEDANCE - TSY MITOVY / MANDANJALANJA | 75 / 75 Ohm |
| FREQUENCY FREQUENCY | 5MHz ~ 120MHz |
| DETAILED DESCRIPTION | RF Balun 5MHz ~ 120MHz 75 / 75 Ohm 5-SMD, No Lead |

Related Tags

| | | |
|--|---|---|
| Aeroflex (MACOM Technology Solutions) MABA-009852-CF1A40 | Distributor MABA-009852-CF1A40 | Mpamatsy MABA-009852-CF1A40 |
| Vidiny MABA-009852-CF1A40 | Sary MABA-009852-CF1A40 | Sary MABA-009852-CF1A40 |
| MABA-009852-CF1A40 Datasheet PDF | MABA-009852-CF1A40 Download Datasheet | MABA-009852-CF1A40 Datasheet |
| Saham MABA-009852-CF1A40 | Buy MABA-009852-CF1A40 | Vidio ny Aeroflex (MACOM Technology Solutions) MABA-009852-CF1A40 |
| Aeroflex (MACOM Technology Solutions) MABA-009852-CF1A40 | Mpamatsy Aeroflex (MACOM Technology Solutions) | Distributor Aeroflex (MACOM Technology Solutions) |
| Aeroflex (MACOM Technology Solutions) MABA-009852-CF1A40 | Aeroflex Circuit Technology MABA-009852-CF1A40 | Aeroflex MABA-009852-CF1A40 |
| Aeroflex (MACOM Technology Solutions) MABA-009852-CF1A40 | Aeroflex Metelics, Division of MACOM MABA-009852-CF1A40 | M/A-Com Technology Solutions MABA-009852-CF1A40 |
| Metelics (MACOM Technology Solutions) MABA-009852-CF1A40 | MACOM Technology Solutions MABA-009852-CF1A40 | |

Related Products

| | |
|---|---|
|  <p>MABA-009210-CT17TB Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MABA-009210-CT176 Ao amin'ny staaky: 1 pcs</p> <p>RFQ</p> |  <p>MABA-009594-CF18A0 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 5MHZ-200MHZ 1:1 6SMD GW Ao amin'ny staaky: 353 pcs</p> <p>RFQ</p> |
|  <p>MABA-009594-CF18TB Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MABA-009594-CF18A Ao amin'ny staaky: 2 pcs</p> <p>RFQ</p> |  <p>MABA-010125-TC1113 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 4.5MHZ-3GHZ 1:1 6SMD FLAT Ao amin'ny staaky: 4 pcs</p> <p>RFQ</p> |
|  <p>MABA-010441-CT38A0 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 5MHZ-1.2GHZ 50/75 4SMD MOD Ao amin'ny staaky: Out stock</p> <p>RFQ</p> |  <p>MABA-009572-CF18A0 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 5MHZ-200MHZ 75/75 6SMD GW Ao amin'ny staaky: Out stock</p> <p>RFQ</p> |
|  <p>MABA-009210-CT1760 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 50MHZ-1.2GHZ 1:1 4SMD Ao amin'ny staaky: Out stock</p> <p>RFQ</p> |  <p>MABA-009274-TC11T2 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 1:1 6SMD FLAT LEAD Ao amin'ny staaky: Out stock</p> <p>RFQ</p> |
|  <p>MABA-010129-CT4A40 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 5MHZ-1.2GHZ 50/75 6SMD GW Ao amin'ny staaky: Out stock</p> <p>RFQ</p> |  <p>MABA-010125-TC1113 Manufacturers: M/A-Com Technology Solutions Description: E-SERIES TRANSFORMER 4.5-3000MHZ Ao amin'ny staaky: Out stock</p> <p>RFQ</p> |
|  <p>MABA-010245-CT1160 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 50MHZ-1GHZ 1:1 6SMD FLAT Ao amin'ny staaky: Out stock</p> <p>RFQ</p> |  <p>MABA-010245-CT11TB Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MABA-010245-CT116 Ao amin'ny staaky: 3 pcs</p> <p>RFQ</p> |

