



AVX Corporation


## CP0603D0942AWTR

Part Number:	CP0603D0942AWTR
Manufacturer / Brand:	AVX Corporation
Mombamomba ny vokatra	RF DIR COUPLER 925-960MHZ 0603
Datasheets:	 <a href="#">CP0603D0942AWTR.pdf</a>
RoHS Status	 Mitahiry ny lead / RoHS tsy mifanaraka
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

[MANGATAHA FAMPISEHOANA](#)

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.

### Specifications of CP0603D0942AWTR

PART NUMBER	CP0603D0942AWTR
MANUFACTURER	AVX Corporation
DESCRIPTION	RF DIR COUPLER 925-960MHZ 0603
LEAD FREE STATUS / ROHS STATUS	Mitahiry ny lead / RoHS tsy mifanaraka
TAKELA-DAZA	 <a href="#">CP0603D0942AWTR.pdf</a>
PACKAGE DEVICE DEVICE	0603
SERIES	-
RETURN LOSS	21dB
POWER - MAX	3W
FONOSANA	Tape & Reel (TR)
PACKAGE / CASE	0603 (1608 Metric)
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
MPANAZATRA STANDARD LEAD TIME	10 Weeks
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
FITOKANA-MONINA	-33dB
LOZAM-PIFAMOIVOIZANA	0.5dB
FREQUENCY	925MHz ~ 960MHz
DETAILED DESCRIPTION	RF Directional Coupler E-GSM 925MHz ~ 960MHz 12.5dB 3W 0603 (1608 Metric)
MPIFANARAKA	12.5dB
COUPLER TYPE	Standard
APPLICATIONS	E-GSM

### Related Tags

AVX Corporation CP0603D0942AWTR	Distributor CP0603D0942AWTR	Mpamatsy CP0603D0942AWTR
Vidiny CP0603D0942AWTR	Sary CP0603D0942AWTR	Sary CP0603D0942AWTR
CP0603D0942AWTR Datasheet PDF	CP0603D0942AWTR Download Datasheet	CP0603D0942AWTR Datasheet
Saham CP0603D0942AWTR	Buy CP0603D0942AWTR	Vidio ny AVX Corporation CP0603D0942AWTR
AVX Corporation CP0603D0942AWTR	Mpamatsy AVX Corporation	Distributor AVX Corporation
AVX Corporation CP0603D0942AWTR	AVX Corporation [MIL] CP0603D0942AWTR	

### Related Products

 <p><b>CP0603D1441AWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.429-1.453GHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603D0863BWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 863MHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0603D2442AWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 2.4-2.484GHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603D0897AWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 880-915MHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0603D0947AWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 935-960MHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603D0880AWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 880MHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0603D0902AWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 890-915MHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603D1880BWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.85-1.91GHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0603D1890BWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.88-1.9GHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603D1034AWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 1.034GHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>CP0603D0881AWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 869-894MHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>CP0603D0837AWTR</b> Manufacturers: AVX Corporation Description: RF DIR COUPLER 837MHZ 0603 Ao amin'ny staoky: Out stock</p> <p><a href="#">RFQ</a></p>