


2450BL15B100E

Part Number:	2450BL15B100E
Manufacturer / Brand:	Johanson Technology
Mombamomba ny vokatra	BALUN 2.4GHZ-2.5GHZ 50/100 0805
Datasheets:	PDF 2450BL15B100E.pdf
RoHS Status	 Lead free / RoHS compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

[MANGATAHA FAMPISEHOANA](#)

Mety ho sary ny sary. Jereo manokana ny tsipiriany momba ny vokatra.













Specifications of 2450BL15B100E

PART NUMBER	2450BL15B100E
MANUFACTURER	Johanson Technology
DESCRIPTION	BALUN 2.4GHZ-2.5GHZ 50/100 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS compliant
TAKELA-DAZA	PDF 2450BL15B100E.pdf
SERIES	2450
MIVERINA MITSOAKA (MIN)	9.5dB
DINGANA FIVOAHANA	180° ±10°
FONOSANA	Cut Tape (CT)
PACKAGE / CASE	0805 (2012 Metric)
ANARANA HAFA	712-1041-1
TENDROMBOHITRA	Surface Mount
NY HAAVON'NY FAHITAN-TORY (MSL)	1 (Unlimited)
MPANAZATRA STANDARD LEAD TIME	11 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
ADI-HEVITRA MITOKA-MONINA (MAX)	1.0dB
IMPEDANCE - TSY MITOVY / MANDANJALANJA	50 / 100 Ohm
FREQUENCY FREQUENCY	2.4GHz ~ 2.5GHz
DETAILED DESCRIPTION	RF Balun 2.4GHz ~ 2.5GHz 50 / 100 Ohm 0805 (2012 Metric)

Related Tags

Johanson Technology 2450BL15B100E	Distributor 2450BL15B100E	Mpamatsy 2450BL15B100E
Vidiny 2450BL15B100E	Sary 2450BL15B100E	Sary 2450BL15B100E
2450BL15B100E Datasheet PDF	2450BL15B100E Download Datasheet	2450BL15B100E Datasheet
Saham 2450BL15B100E	Buy 2450BL15B100E	Vidio ny Johanson Technology 2450BL15B100E
Johanson Technology 2450BL15B100E	Mpamatsy Johanson Technology	Distributor Johanson Technology
Johanson Technology 2450BL15B100E	Johanson 2450BL15B100E	Johanson Technology Inc. 2450BL15B100E

Related Products

 <p>2450BL14B200T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/200 0603 Ao amin'ny staoky: Out stock</p> <p>RFQ</p>	 <p>2450BL15B200E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 Ao amin'ny staoky: Out stock</p> <p>RFQ</p>
 <p>2450BL15B050E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 0805 Ao amin'ny staoky: Out stock</p> <p>RFQ</p>	 <p>2450BM08B0003T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 SSMD Ao amin'ny staoky: Out stock</p> <p>RFQ</p>
 <p>2450BL15K050E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 0805 Ao amin'ny staoky: Out stock</p> <p>RFQ</p>	 <p>2450BL14B100T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 Ao amin'ny staoky: Out stock</p> <p>RFQ</p>
 <p>2450BL15K100E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 Ao amin'ny staoky: Out stock</p> <p>RFQ</p>	 <p>2450BL14C200T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/200 0603 Ao amin'ny staoky: Out stock</p> <p>RFQ</p>
 <p>2450BL14B100 Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 Ao amin'ny staoky: Out stock</p> <p>RFQ</p>	 <p>2450BL15B150E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/150 0805 Ao amin'ny staoky: Out stock</p> <p>RFQ</p>
 <p>2450BL14C050T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Ao amin'ny staoky: Out stock</p> <p>RFQ</p>	 <p>2450BM07A0004T Manufacturers: Johanson Technology Description: BALUN MATCHED EIA0402 Ao amin'ny staoky: Out stock</p> <p>RFQ</p>